The McGraw-Hill Companies

Chapter 5 Image Slides



5-1 Drive Shaft Failure



5-2 Hub Failure



5-3 Bolt Failure



5-4 Test Fixture Failure



5-5 Spring Failure



5-6 Idealized Stress-Strain Curve



5-7 Max Shear-StressThy(MSS)



5-8 Triaxial Stress



5-9 Distortion-Energy Thy. (DE)



5-10 Octahedral Surfaces



EXAMPLE 5–1

3