

## **Sketching Assignment #6**

### **Reading Assignment:**


Read the following chapter in Engineering Graphics Workbook, Series 1.2 by Craig & Craig:  
Chapter J - Sectional Views

### **Sketching Assignment:** (staple all sheets together in the order assigned before submitting)

Chapter J: Complete worksheets S-1, S-2, and S-3 (include a cutting-plane line on S-1)


Handout: Attached full section drawings (#1 and #3). Be sure to include a cutting-plane line in each part. Make lines dark so that they can be easily seen.

1



CLUTCH STOP

Sketch top view  
in full section.



3

INJECTOR BASE

Sketch top view  
in full section.

