

Most people would rather die than think;
in fact, they do so.

—Bertrand Russell

Tempering

Fresh MAR too brittle - infrequently used

Brittle materials can be used in compression

Ex: fresh MAR in ball bearings

Martensite (MAR)

TEMPERING MAKES MAR TOUGH

